
4 ALBERT EMBANKMENT
LONDON SE1 7SR
Telephone: +44 (0)20 7735 7611 Fax: +44 (0)20 7587 3210

MEPC.1/Circ.777
20 January 2012

IMPLEMENTATION AND ENFORCEMENT OF MARPOL ANNEX VI

Bunker delivery note and fuel oil sampling

Communication received from the Administration of Liberia

- 1 A communication has been received from the Administration of Liberia concerning the application of provisions under MARPOL Annex VI.
- 2 In accordance with the provisions of regulation 18.9.6 of MARPOL Annex VI, the above-mentioned communication, summarized in the annex, is circulated to Parties to the 1997 Protocol for their information and appropriate action, as well as to all IMO Members.
- 3 Reference should be made to MEPC.1/Circ.508 on bunker delivery notes and fuel oil sampling, and resolution MEPC.96(47) on Guidelines for the Sampling of Fuel Oil for Determination of Compliance with MARPOL Annex VI.
- 4 For further details, please contact the Flag State Administration, the bunkering port Authorities or the marine fuel oil supplier.

ANNEX

SUMMARY OF NOTES OF PROTEST RELATED TO MARPOL ANNEX VI
RECEIVED FROM JULY TO DECEMBER 2011

Notes of protest received from the Administration of Liberia

Name of ship, IMO number	Bunkering port, Country, Date	Supplier's Name, address, telephone number	Non-compliance issues
JONNI RITSCHER 933383	Antwerp, Belgium, 1.7.2011	O.W.Bunker, -----, -----	The sulphur content on BDN: 0.97% m/m, The sulphur content after supplied and tested: 1.02% m/m
CMA CGM TOGO 9337028	Rotterdam, the Netherlands, 5.7.2011	Verbeke Bunkering NV, Nijverheidsstraat 7 B-2960 St. Job in't Goor Belgium, +32 3 652 06 08	The sulphur content on BDN: 0.92% m/m, The sulphur content after supplied and tested: 1.06% m/m
CMA CGM COMOE 9339868	Rotterdam, the Netherlands, 14.7.2011	Lukoil Benelux B.V., De Linie 1, 2905 AX Capelle aan den IJssel the Netherlands, +31 10 264 2700	The sulphur content on BDN: 0.97% m/m, The sulphur content after supplied and tested: 1.04% m/m
CMA CGM COMOE 9339868	Rotterdam, the Netherlands, 26.7.2011	North Sea Group Bunkering B.V., Laan van Barcelona 800 3317 DD Dordrecht the Netherlands, +31 88 1007	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.03% m/m
HANSA MARBURG 9334818	Antwerp, Belgium, 30.7.2011	Verbeke Bunkering NV, Nijverheidsstraat 7 B-2960 St. Job in't Goor Belgium, +32 3 652 06 08	The sulphur content on BDN: 0.90% m/m, The sulphur content after supplied and tested: 1.02% m/m
CARLOTTA STAR 9210050	Rotterdam, the Netherlands, 11.8.2011	BP Marine, Rivium Boulevard 301 2909 LK Capelle a/d IJssel the Netherlands, +31 10 249 1523	The sulphur content on BDN: 0.98% m/m, The sulphur content after supplied and tested: 1.02% m/m
HELLE RITSCHER 9333371	Antwerp, Belgium, 22.8.2011	Verbeke, -----, -----	The sulphur content on BDN: 1.00% m/m, The sulphur content after supplied and tested: 1.04% m/m
CMA CGM COMOE 9339868	Rotterdam, the Netherlands, 6.9.2011	Verbeke Bunkering NV, Nijverheidsstraat 7 B-2960 St. Job in't Goor Belgium, +32 3 652 06 08	The sulphur content on BDN: 0.92% m/m, The sulphur content after supplied and tested: 1.06% m/m

Name of ship, IMO number	Bunkering port, Country, Date	Supplier's Name, address, telephone number	Non-compliance issues
AENNE RICKMERS 9152753	Antwerp, Belgium, 17.9.2011	O.W. Bunker, -----, -----	The sulphur content on BDN: 0.97% m/m, The sulphur content after supplied and tested: 1.02% m/m
NS POINT 9329655	Antwerp, Belgium, 5.10.2011	Verbeke Bunkering NV, Nijverheidsstraat 7 B-2960 St. Job in't Goor Belgium, +32 3 652 06 08	The sulphur content on BDN: 1.00% m/m, The sulphur content after supplied and tested: 1.06% m/m
CMA CGM COMOE 9339868	Rotterdam, the Netherlands, 19.10.2011	Lukoil Benelux B.V., De Linie 1, 2905 AX Capelle aan den IJssel the Netherlands, +31 10 264 2700	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.02% m/m
AENNE RICKMERS 9152753	Antwerp, Belgium, 31.10.2011	Ocean Energy Belgium bvba, Maritime House Noorderlaan 111 Antwerpen 2030 Belgium, +32 3 301 03 41	The sulphur content on BDN: 0.99% m/m, The sulphur content after supplied and tested: 1.05% m/m