Subject: Technical Information No. 2011-003 Unified Interpretation of SOLAS Reg.II-1/3-5

Number: CLD/9/2939 Date: 2 Jan. 2011 شماره: ۹/۲۹۳۹/ق م تاریخ : ۸۹/۱۰/۱۲



All respectful ICS surveyors

With my gratitude, respectfully,

Please consider the document related to the above mentioned subject which is maintained at following address in ICS Network (ICS-WAN):

<u>\\server\ICS</u> Organization\Convention and legislation Department\Publications\TECH

Also the Hard Copy and Electronic File of the above mentioned document would be mailed to all ICS branch offices.

A. Jamaly Manager of Convention & Legislation Department Iranian Classification Society – ICS کلیه بازرسان محترم ICS

توسط پست ارسال می گردد.

با سلام احتراماً سند مربوط به موضوع فوقالذکر را جهت انجام بهرهبرداریهای لازم ملاحظه فرمائید. سند مذکور در شبکه داخلی موسسه با آدرس ذیل قابل دسترسی میباشد:

<u>\\Server\ICS Organization\Convention and legislation</u> <u>Department\Publications\TECH</u> همچنین نسخه الکترونیکی و هارد کپی این سند به کلیه شعب موسسه نیز

عبدالله جمالي

مدیریت واحد کنوانسیون ها و مقررات دریایی موسسه رکم بندی ایرانیان

Contents

1. Introduction		3
1.1	General	3
1.2	Changes	3
2. Unified Interpretation of SOLAS		
Reg.II-1	/3-5	3
2.1	Adoption	3
2.2	Technical History	3
2.3	Summary	3
3. References		

1. Introduction

1.1 General

This publication presents one of the outcomes of MSC 88th Committee which is related to installation of materials which contain asbestos.

The electronic file of this document is available in

the ICS network with the following address: <u>\\server\ICS Organization\Convention and</u> legislation Department\ Publications\ TECH

1.2 Changes

This edition dated 2010.Jan.01 and any other necessary changes related to this document will be announced after this date.

2. Unified Interpretation of SOLAS Reg.II-1/3-5

2.1 Adoption

The Maritime Safety Committee, at its 88th session, approved MSC.1/Circ.1379 which is the unified interpretation of "new installation of materials is containing asbestos" in SOLAS Reg.II-1/3-5. Please refer to the following notice for the background and the content of this unified interpretation.

2.2 Technical History

The Maritime Safety Committee, at its 86th session, adopted the amendment to SOLAS Reg.II-1/3-5 by Res.MSC.282 (86), according to which, new installation of materials containing asbestos shall be prohibited as follows:

- Application: From 1 January 2011, for all ships, new installation of materials which contain asbestos shall be prohibited.
- The installation of materials containing asbestos has been prohibited with certain exceptions, but those exceptions are deleted, so all new installation of materials containing asbestos shall be prohibited from 1 January 2011.

During discussion for the adoption of the above amendment, there had been an opinion that a new paragraph should be added to SOLAS regulation II-1/3-5, adding a definition of 'new installation of materials containing asbestos', but the Committee had instructed DE Sub-Committee to consider the matter further.

DE Sub-Committee, at its 53rd session, agreed to the draft MSC circular on Unified Interpretation of SOLAS regulation II-1/3-5, as set out in the ensuing paragraph 2, for submission to MSC 88 for approval. Subsequently, MSC 88 approved it as MSC.1/Circ.1379.

2.3 Summary

Unified Interpretation of "new installation of materials containing asbestos" in SOLAS Chapter II-1 Regulation 3-5 (MSC.1/Circ.1379) in the context of this regulation, 'new installation of materials containing asbestos' means any new physical installation on board. Any material purchased prior to 1 January 2011 being kept in the ship's store or in the shipyard for a ship under construction, should not be permitted to be installed after 1 January 2011 as a working part.

3. References

IMO Publications